Weather Skin Mastic Page 1 of 4

MATERIAL SAFETY DATA SHEET

DAS Manufacturing Inc. 3610 Cinnamon Trace Dr Valrico, FL 33594

INFORMATION: (813) 681-6024

EMERGENCY CONTACT: Chemtrec 1-800-424-9300

FAX NO: (813) 681-5807

1/2/14

SECTION I: PRODUCT IDENTIFICATION

PRODUCT NAME: das Curb Marker Adhesive

PRODUCT CODE: RS-222-5 and RS-222-11

HMIS CODES: P: H H: 2 F: 3 R: 0

SECTION II: HAZARDOUS INGREDIENTS/SARA III INFORMATION

| REPORTABLE COMPONENTS | CAS NUMBER | OSHA PEL | ACGIH TLV | WEIGHT PERCENT |
|--|------------|----------|-----------|-----------------------|
| *Toluene Rubber, Resin, Filler (Non-Hazardous) | 108-88-3 | 200 PPM | 100 PPM | 30 - 40 % 60 -70 % |

*SARA

SECTION III: PHYSICAL/CHEMICAL CHARACTERISTICS

SPECIFIC GRAVITY: 1.5 BOILING RANGE: 231°F EVAPORATION RATE: 1+ SOLUBILITY IN WATER: None REACTIVITY IN WATER: None

MATERIAL VOC: 3.25 lbs/gal **APPEARANCE AND ODOR:** Thick black paste, **COATING VOC:** 3.25 lbs/gal

solvent odor

DENSITY: Heavier than air

Weather Skin Mastic Page 2 of 4

SECTION IV: FIRE AND EXPLOSION HAZARD DATA

FLASH POINT: 45°F METHOD USED: TCC

FLAMMABLE LIMITS IN AIR BY VOLUME: LOWER: 1.0 UPPER: 7.0

EXTINGUISHING MEDIA:

Class B extinguisher, Carbon Dioxide, Dry Chemical, Foam

SPECIAL FIREFIGHTING PROCEDURES:

Respiratory equipment should be worn to avoid inhalation of concentrated vapors. Water should not be used except as fog to keep nearby containers cool.

UNUSUAL FIRE AND EXPLOSION HAZARDS:

Closed containers may explode when exposed to extreme heat.

SECTION V: REACTIVITY DATA

STABILITY: Stable

CONDITIONS TO AVOID: Sources of ignition

INCOMPATIBILITY (MATERIALS TO AVOID): Strong acids & oxidizers, liquid chlorine & oxygen

HAZARDOUS DECOMPOSITION OR BY-PRODUCTS: Normal combustion products

HAZARDOUS POLYMERIZATION: Will not occur

SECTION VI: HEALTH HAZARD DATA

ROUTES OF ENTRY: Inhalation: Yes Skin: Yes Ingestion: Yes

INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE:

High vapor concentrations are irritating to eyes and respiratory tract. May cause headache and dizziness.

Weather Skin Mastic Page 3 of 4

SKIN AND EYE CONTACT HEALTH RISKS AND SYMPTOMS OF EXPOSURE:

May cause irritation on prolonged contact, redness. Wash affected area with warm soapy water. Do not use solvents.

EYE HEALTH RISKS AND SYMPTOMS OF EXPOSURE:

Irritation and soreness. Irrigate with copious quantities of water and seek medical attention immediately.

INGESTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE:

No adverse effects are expected to occur. Could produce a laxative effect and may be irritating to the digestive tract.

HEALTH HAZARDS (ACUTE AND CHRONIC):

May cause dizziness or narcosis in high vapor concentrations. Will cause defating of skin. Effects are reversible. Long term exposure (years) vapor may cause lung, liver or kidney damage. The solvents listed have been reported to affect the central nervous system.

CARCINOGENICITY: NTP CARCINOGEN: No IARC MONOGRAPHS: No OSHA REGULATED:

Combustible

MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE:

Generally aggravated by exposure respiratory if very high concentration.

EMERGENCY AND FIRST AID PROCEDURES:

Give oxygen, do not induce vomiting - gastric lavage - wash eyes and skin with water.

SECTION VII: PRECAUTIONS FOR SAFE HANDLING AND USE

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED:

Soak up with absorbent. Shovel into waste container. Flush area with soap and water solution.

WASTE DISPOSAL METHOD:

Recover material and dispose of in accordance with federal, state, and local regulations.

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING:

Store and handle to prevent contamination from any source.

OTHER PRECAUTIONS:

Excessive skin contact may defat skin causing dermatitis.

Weather Skin Mastic Page 4 of 4

SECTION VIII: CONTROL MEASURES

RESPIRATORY PROTECTION:

Self contained breathing apparatus if above TLV limit exceeding.

VENTILATION:

Local Exhaust: Yes Special: None Mechanical (General): None Other: None

SKIN PROTECTION:

Barrier cream recommended.

EYE PROTECTION:

Wear eye protection.

OTHER PROTECTIVE CLOTHING OR EQUIPMENT:

Protective gloves (neoprene, viton), long sleeves and long pants.

WORK/HYGIENIC PRACTICES:

Do not smoke while using. Wash hands after use. Avoid unnecessary exposure and removal of the material from skin and clothing.

SECTION IX: DISCLAIMER

All chemical compounds marked with an asterisk (*) are toxic chemicals subject to the reporting requirements of Section 313 of Title III of the Super Fund Amendments and Reauthorization Act (SARA) of 1906 and 40 CFR Part 372. You must notify each person to whom this mixture or trade name product is sold. This statement must remain a part of this Material Safety Data Sheet shall include this statement.